

FUSE BLOCK DETAILS


MY 1986-1989

FROM PAGE 105

HOT IN ACCY RUN OR START

FROM PAGE 105

HOT AT ALL TIMES



REVISIONS: ① ANTI-TOWING SENSOR NOT USED AS OF CHASSIS END NUMBER A298949, F017692

② UP TO APRIL 1987 PRODUCTION

③ AS OF APRIL 1987 PRODUCTION

④ 300CE ONLY

⑤ ON 300CE MODELS ONLY, POWER IS NOT TAKEN FROM X30 BUT RATHER FROM X18 PIN 3

109/2

124.0/1

Supplement 10